

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #33-1 PAD

Location ID: 315162

Date: 08/15/2025



Photo # 1948 Entrance to location



Photo # 1959 Location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #33-1 PAD

Location ID: 315162

Date: 08/15/2025



Photo # 1949 Location



Photo # 1956 Location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #33-1 PAD

Location ID: 315162

Date: 08/15/2025



Photo # 1983 NW corner of location

Photo # 1984 NE corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #33-1 PAD

Location ID: 315162

Date: 08/15/2025



Photo # 1985 SE corner of location



Photo # 1986 SW corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #33-1 PAD

Location ID: 315162

Date: 08/15/2025



**Photo # 1979 Open ended piping/wildlife hazard/available for entry by wildlife**



**Photo # 1980 Debris**

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #33-1 PAD

Location ID: 315162

Date: 08/15/2025



Photo # 1981 Debris

Photo # 1995 Debris