

Inspection Photos
Location Name: UPRR 23 PAN AM D#3
Location ID: 319938



Photo#1 Wellhead/Corrective Actions have been addressed

Photo#2 Separator/Gas Meter/Corrective Actions have been addressed

Inspection Photos
Location Name: UPRR 23 PAN AM D#3
Location ID: 319938



Photo#3 Production Tanks/Corrective Actions have been addressed