

Final Reclamation and Stormwater Inspection

August 15, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 318275

Location Name: JAMES S HALEY TRUSTEE B #3

Inspection Document #: 718600878

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: JAMES S HALEY TRUSTEE B #3
Location ID: 318275



Photo 1. Looking east down the access road towards the well location. The access road appears to have desirable perennial vegetation progressing towards 80% coverage of the reference area.



Photo 2. Looking east from the wellbore. Desirable perennial vegetation is present on the location and appears to be progressing towards 80% coverage of the reference area. Undesirable weeds such as kochia and List B noxious weed musk thistle is also present on location.

Inspection Photos
Location Name: JAMES S HALEY TRUSTEE B #3
Location ID: 318275



Photo 3. Looking north from the wellbore. See photo 2 comments.



Photo 4. Looking west from the wellbore. See photo 2 comments.



Inspection Photos
Location Name: JAMES S HALEY TRUSTEE B #3
Location ID: 318275



Photo 5. Looking south from the wellbore. See photo 2 comments.



Photo 6. Picture taken on the east side of the location near the wellbore. List B noxious weed musk thistle.

Inspection Photos
Location Name: JAMES S HALEY TRUSTEE B #3
Location ID: 318275



Photo 7. Picture taken east of the wellbore looking south. Oilfield pipe on location.



Photo 8. Reference area to the north of the location.