

Final Reclamation and Stormwater Inspection

August 15, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 333204

Location Name: GRANT BROTHERS 41-11-61N68W/11NENE

Inspection Document #: 718600876

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GRANT BROTHERS
41-11-61N68W/11NENE
Location ID: 333204



Photo 1. Looking north across well API 123-22388 and the tank battery location. No oil and gas equipment remains on location. The entire location has hard packed gravel/riprap from when it was used as a parking lot.



Photo 2. Looking north across the east side of the tank battery approximately where midstream equipment was located. No equipment remains.



Inspection Photos
Location Name: GRANT BROTHERS
41-11-61N68W/11NENE
Location ID: 333204



Photo 3. Looking south across the location. See photo 1 comments.



Photo 4. Looking south across well API 123-08448 no equipment remains.



Inspection Photos
Location Name: GRANT BROTHERS
41-11-61N68W/11NENE
Location ID: 333204



Photo 5. Google earth aerial imagery taken 04/21/2022. The location (red circle) underwent a land use change to storage yard/parking lot which has since been abandoned.

