

Interim Reclamation Inspection

August 18, 2025

Operator: SMITH ENERGY LLC - 10536

Location ID: 474257

Inspection Document #: 718800716

Yuma County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: SALLY CLARKE-64N46W/3NENW

Location ID: 474257



Photo 1. Photo taken of the tank battery location, facing west. Photo illustrates an unsecured saltwater tank and fluid within the bermed area surrounding the tank.



Photo 2. Photo taken of the tank battery location, facing west. Weedy annual vegetation, including kochia (*Bassia scoparia*), was observed surrounding the location.



Inspection Photos

Location Name: SALLY CLARKE-64N46W/3NENW

Location ID: 474257



Photo 3. Photo taken of the tank battery location, facing southwest. See comments under Photo 1.



Photo 4. Photo taken of the area adjacent to the tank battery location, north of the location, facing west. Photo illustrates some weedy annual vegetation and a patch of bare ground.



Inspection Photos

Location Name: SALLY CLARKE-64N46W/3NENW

Location ID: 474257



Photo 5. Photo taken of the tank battery location, facing northwest. See comments under Photo 1.



Photo 6. Photo taken of the tank battery location, facing east. See comments under Photo 1.



Inspection Photos

Location Name: SALLY CLARKE-64N46W/3NENW

Location ID: 474257



Photo 7. Photo taken of the tank battery location, facing north. See comments under Photo 1.



Photo 8. Photo taken of the tank battery location, facing southwest. See comments under Photo 1.