

Inspection Photos
Location Name: Dorothy Sebold B2
Location ID: 318909



Photo 1 Location overrun with tall vegetation.

Photo 2 Wellhead overrun with tall vegetation & trash.

Inspection Photos
Location Name: Dorothy Sebold B2
Location ID: 318909



Photo 3 Well site sign.

Photo 4 Ancillary equipment overrun with tall vegetation.