

Photo documentation of B14 containment cleanup efforts



Photo of released condensate inside secondary containment.



Photo of the secondary containment following fluid recovery and containment washing.