

Inspection Photos
Location Name: Norbert E Badding-62N68W 22SESE
API # 05-123-09496



Sign

Inspection Photos
Location Name: Norbert E Badding-62N68W 22SESE
API # 05-123-09496



Stained Soil

Stained Soil

Inspection Photos
Location Name: Norbert E Badding-62N68W 22SESE
API # 05-123-09496



Stained Soil

Stained Soil

Inspection Photos
Location Name: Norbert E Badding-62N68W 22SESE
API # 05-123-09496



Stained Soil. Appears operator only placed clean dirt over the top of the stained soil.

Location

Inspection Photos
Location Name: Norbert E Badding-62N68W 22SESE
API # 05-123-09496



Unmarked Riser

Unmarked Riser