

Inspection Photos
Location Name: UPRR 23 PAN AM B2
Location ID: 319928



Photo #1 Tanks & weeds.

Photo #2 Tanks & weeds.

Inspection Photos
Location Name: UPRR 23 PAN AM B2
Location ID: 319928



Photo #3 Separator & weeds

Photo #4 well head & weeds.