



WELL SITE INSPECTION FORM
(DRILLING AND PLUGGING)

✓

Well Name Larson 4-12 API Number 05 - 001 - 8239
 Operator Diamondback Oil Corp Permit # 822078
 Location NWSW 4-25-64W County Adams
 Field Sumboree Inspector EBB

AL/PA/DA Inspection Results: Well Status:
 Pass(Y) Fail(N) Date 3-19-92 ND DG WO PR SI TA

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
 Consistent with APD casing Program? YES NO Returns _____
 Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
 Drilling Pits: Closed Open Wellhead Installed: _____ Sign: Yes No
 Tank ID: Yes No N/A Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
 Equipment _____ Meter Run: Yes No
 Bradenhead Press: _____ Fluid: No Yes Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: 4-19-90 PA
3-5-92 reclaim surface Date Permit Expired: _____
 Hole Plugged: Yes No Pits Backfilled: Yes No
 Material Buried: Yes No N/A Site Clean: Yes No
 Bond Release OK: Yes No Fed Hole Marker: Yes No

Date of Safety/Status Inspection _____

Comments: Near north boundary of Front Range App.
Muddy roads. Plowed

Violations: Yes No Notice Sent: Yes No Date Sent: _____