

Inspection Photos
Location Name: Dillard/20Y-HZ Pad
Location #: 427337



Photo #1

Dillard/20Y-HZ Pad Battery site

Inactive | Shut-down

Equipment documented: Loc. ID 427337



Photo #2

Dillard/20Y-HZ Pad Battery site

Inactive | Shut-down

Wellsite(s), Battery / Facility entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Dillard/20Y-HZ Pad
Location #: 427337



Photo #3

Dillard/20Y-HZ Pad Battery site

Inactive | Shut-down

Crude oil, produced H2O tank(s): SE corner



Photo #4

Dillard/20Y-HZ Pad Battery site

Inactive | Shut-down

ECD(s)



Inspection Photos
Location Name: Dillard/20Y-HZ Pad
Location #: 427337



Photo #5
Dillard/20Y-HZ Pad Battery site
Inactive | Shut-down
Separator(s)



Photo #6
Dillard/20Y-HZ Pad Battery site
Inactive | Shut-down
Compressor(s)



Inspection Photos
Location Name: Dillard/20Y-HZ Pad
Location #: 427337




Photo #7

Dillard/20Y-HZ Pad Battery site

Inactive | Shut-down

Battery / Facility signage



Photo #8

Dillard/20Y-HZ Pad Battery site

Inactive | Shut-down

Tank(s)

CG: Overgrown vegetation



Inspection Photos

Location Name: Dillard/20Y-HZ Pad

Location #: 427337

Associated Well(s)	API	Status
Main pad * <i>East → West</i>		LOC # 427337
1. Dillard 20Y-401	123-36600	TA
2. Dillard 20T-221	123-36602	TA
3. Dillard 20T-401	123-36601	TA

Photo #9

Dillard/20Y-HZ Pad Battery site

Inactive | Shut-down

Associated Well(s)

3: Temporarily Abandoned | TA



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources