

Final Reclamation and Stormwater Inspection

August 20, 2025

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 320378

Well Name: FOSTER #1-22

Inspection Document #: 718600882

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: FOSTER #1-22
Location ID: 320378



Photo 1. Picture taken at the center of the access road. Culvert is part of the irrigation system and appears to be used for landowner access to the field. List B noxious weed scotch thistle is present on the access road.



Photo 2. Picture taken near the entrance of the access road. List B noxious weed scotch thistle. Scotch thistle rosettes were observed on the length of the access road.

Inspection Photos
Location Name: FOSTER #1-22
Location ID: 320378



Photo 3. Looking east down the access road towards the well location. The location and access road are located within a mowed field. It appears that desirable vegetation has established on the access road.



Photo 4. Looking south from the wellbore. the well location has been mowed. No oil and gas equipment remains on location. List B noxious weed scotch thistle rosettes were observed on the well location along with other undesirable weeds such as kochia. It appears that desirable vegetation has established on location and is progressing towards 80% coverage of the reference area.



Inspection Photos
Location Name: FOSTER #1-22
Location ID: 320378



Photo 5. Looking east from wellbore. See photo 4 comments.



Photo 6. Looking north from wellbore. See photo 4 comments.



Inspection Photos
Location Name: FOSTER #1-22
Location ID: 320378



Photo 7. Looking west from wellbore. See photo 4 comments.



Photo 8. Reference vegetation to the south of well location. Reference vegetation appears to be poor.

