

Final Reclamation and Stormwater Inspection

August 20, 2025

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 320204

Well Name: POITZ #1-22

Inspection Document #: 718600884

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: POITZ #1-22
Location ID: 320204



Photo 1. Looking east down the former access road to the wellhead. No oil and gas equipment is present on location. Desirable vegetation was not observed on location. Vegetation consists of undesirable weedy species such as kochia and list C noxious weed field bindweed. A prairie dog colony is present on location.



Photo 2. Looking north from the wellhead. This location was surrounded by gravel and abortion remains as an access road to a power substation.



Inspection Photos
Location Name: POITZ #1-22
Location ID: 320204



Photo 3. Looking east from the well location. See photo 1 comments.



Photo 4. Looking east from the well location. See photo 1 comments.

Inspection Photos
Location Name: POITZ #1-22
Location ID: 320204



Photo 5. Looking west from the well location. See photo 1 comments.



Photo 6. Looking east across the former tank battery. No equipment remains. Vegetation consists of undesirable weedy species such as kochia and list C noxious weed field bindweed.



Inspection Photos
Location Name: POITZ #1-22
Location ID: 320204



Photo 7. Picture taken at the east side of the location looking south. List B noxious weed Canada thistle was observed just outside the location. Noxious weeds were not observed on location at the time of inspection and appear to have been controlled on location.



Photo 8. Reference vegetation to the east of the location.

