


Inspection Photos  
Location Name: HAUGEN 1-30  
Location ID: 319699



Photo#1 Pumpjack/**CA:Weeds uncontrolled throughout pumpjack**

Photo#2 Production Tank/Separator/(2)ECDS/Gas Meter/**CA:Weeds uncontrolled throughout location**

Inspection Photos  
Location Name: HAUGEN 1-30  
Location ID: 319699



Photo#3 CA:Weeds uncontrolled throughout location

Photo#4 CA:Weeds uncontrolled throughout location