

Inspection Photos

Location Name: PARMLEE-63N62W/1SWNW

Location #: 327604



Photo #1

Parmlee #3 (123-14916) Wellsite

Shut-In | SI

CA: Overgrown Vegetation



Photo #2

Parmlee #3 Wellsite

Shut-In | SI

**CA: Overgrown Vegetation;
Post Emergency # & Company name**



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: PARMLEE-63N62W/1SWNW

Location #: 327604



Colorado Energy & Carbon Management Commission
Weld County
+40.256602, -104.279404
31D° NW
2025-08-15 12:25

Photo #3

Parmlee #3 Wellsite

Shut-In | SI; Portable tank

CA: Overgrown Vegetation



Colorado Energy & Carbon Management Commission
Weld County
+40.256604, -104.275215
31D° NW
2025-08-15 12:52

Photo #4

Parmlee #3 Battery site

Inactive | Shut-down

Equipment documented: Loc. ID 327604



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: PARMLEE-63N62W/1SWNW

Location #: 327604



Colorado Energy & Carbon Management Commission
Weld County
+40.262342, -104.274778
197° S
2025-08-15 13:06

Photo #5

Parmlee #3 Battery site
Inactive | Shut-down
Wellsite(s), Battery entrance
~ 4/10 mile(s)



Colorado Energy & Carbon Management Commission
Weld County
+40.239716, -104.206706
273° W
2025-08-15 13:30

Photo #6

Parmlee #3 Battery site
Inactive | Shut-down
Wellsite(s), Battery entrance
~ 4.0 mile(s)



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources