

Inspection Photos

Location Name: PARMLEE-63N62W/1SWNW

Location #: 327604



Photo #1

Parmlee #3 Battery site

Inactive | Shut-down

Equipment documented: Loc. ID 327604



Photo #2

Parmlee #3 Battery site

Inactive | Shut-down

Wellsite(s), Battery entrance

~ 4/10 mile(s)



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: PARMLEE-63N62W/1SWNW

Location #: 327604



Photo #3

Parmlee #3 Battery site
Inactive | Shut-down
Well(s)ite(s), Battery entrance
~ 4.0 mile(s)



Photo #4

Parmlee #3 Battery site
Inactive | Shut-down
Crude Oil tank(s); SE corner
CA: Overgrown Vegetation



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: PARMLEE-63N62W/1SWNW

Location #: 327604



Photo #5

Parmlee #3 Battery site

Inactive | Shut-down

Produced H₂O tank(s); SE corner

CA: Overgrown Vegetation



Photo #6

Parmlee #3 Battery site

Inactive | Shut-down

Treater(s), Separator(s)

CA: Overgrown Vegetation



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: PARMLEE-63N62W/1SWNW

Location #: 327604



Colorado Energy & Carbon Management Commission
Weld County
+40.256731,-104.275548
220° SW
2023-08-15-12:53

Photo #7

Parmlee #3 Battery site

Inactive | Shut-down

Battery signage

CA: Overgrown Vegetation



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: PARMLEE-63N62W/1SWNW

Location #: 327604

Associated Well(s)	API	Location	Status
1. Parmlee #3	123-14916	327604	SI

Photo #8

Parmlee #3 Battery site

Inactive | Shut-down

Associated well(s)

Shut-In | SI



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources