

Inspection Photos

08/13/2025

Operator: QB Energy Operating LLC #10844

Location ID: 334679

Inspection Doc: 719200108

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334679



Photo 1: Photos show an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334679



Photo 2: Photos show an overview of the location looking east and southwest, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334679



Photo 3: Photos shows an example of barbed-wire fencing surrounding the location that appears to be in disrepair. Comply with Rule 603.h.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334679



Photo 4: Photos show an example of sediment tracking throughout the location. Maintenance is advised.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334679



Photo 5: Photos shows a stormwater outlet at the northwestern portion of the pad. Sediment has accumulated and the outlet does not appear to be sufficiently armored. Maintenance is advised.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources