

WELL NAME: ITTY BITTY 12-31, API #: 071-08232, INSP. # 716301428



PHOTO 1: WELL SIGN




**PHOTO 2: LOCATION.**



**PHOTO 3: WELLHEAD AND EQUIPMENT.**





**PHOTO 4: OILY WASTE IN PRIME MOVER ENGINE SKID (ALTHOUGH IT APPEARS THAT THE SKID HAS BEEN CLEANED SINCE LAST INSPECTION THE EQUIPMENT MAINTANANCE HAS EITHER NOT BEEN PERFORMED OR REPAIRS ARE INADEQUATE). DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. ( THIS IS THE 3<sup>RD</sup> INSPECTION OF THIS EQUIPMENT WITH THE SAME COMPLIANCE CONDITIONS LEAKING EQUIPMENT MUST BE REPAIRED OR REPLACED. THIS IS THE 3<sup>RD</sup> NOTICE TO FIX LEAKING EQUIPMENT IMMEDIATE ACTION IS REQUIRED.**