

Final Reclamation Inspection

August 5, 2025

Operator: FOUNDATION ENERGY MANAGEMENT LLC -
10112

Location ID: 429230

Inspection Document #: 718800676

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GREEN #1-7
Location ID: 429230



Photo 1. Photo taken of the abandoned well location, facing north. Photo illustrates that there is no evidence of oil and gas disturbance at the location and based on records the well was never drilled.



Photo 2. Photo taken of the abandoned well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: GREEN #1-7
Location ID: 429230



Photo 3. Photo taken of the abandoned well location, facing South. See comments under Photo 1.



Photo 4. Photo taken of the abandoned well location, facing West. See comments under Photo 1.

