

# Final Reclamation Inspection

August 5, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 405695

Inspection Document #: 718800678

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: STATE #1  
Location ID: 405695



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but the location does not meet Rule 1004 standards as the site is dominated by weedy annual vegetation, including kochia (*Bassia scoparia*).



**Photo 2.** Photo taken of the well location, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: STATE #1  
Location ID: 405695



**Photo 3.** Photo taken of the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: STATE #1  
Location ID: 405695



**Photo 5.** Photo taken of ground cover at the well location. Photo illustrates kochia (*Bassia scoparia*) dominates the site.



**Photo 6.** Photo taken of the well location, facing southeast. See comments under Photo 1.



Inspection Photos  
Location Name: STATE #1  
Location ID: 405695



**Photo 7.** Photo taken of the reference area to the location, north of the location, facing north. Photo illustrates perennial grass vegetation.