

# Final Reclamation Inspection

August 5, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 423929

Inspection Document #: 718800685

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: MONTANA STATE PC LG #16-68HN

Location ID: 423929



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but the location does not meet Rule 1004 standards. Weedy annual vegetation, including kochia (*Bassia scoparia*), was observed across the location.



**Photo 2.** Photo taken of the well location, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: MONTANA STATE PC LG  
#16-68HN  
Location ID: 423929



**Photo 3.** Photo taken of the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing West. See comments under Photo 1.

## Inspection Photos

Location Name: MONTANA STATE PC LG

#16-68HN

Location ID: 423929



**Photo 5.** Photo taken of ground cover at the well location. Photo illustrates kochia (*Bassia scoparia*) and patches of bare ground.



**Photo 6.** Photo taken of the access road to the well location, facing north, towards the location. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation does not meet Rule 1004 standards.



Inspection Photos  
Location Name: MONTANA STATE PC LG  
#16-68HN  
Location ID: 423929



**Photo 7.** Photo taken of the access road to the location, facing south. See comments under Photo 6.



**Photo 8.** Photo taken of the tank battery location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards. The location is dominated by kochia (*Bassia scoparia*).



Inspection Photos

Location Name: MONTANA STATE PC LG

#16-68HN

Location ID: 423929



**Photo 9.** Photo taken of the tank battery location, facing south. See comments under Photo 8.



**Photo 10.** Photo taken of the tank battery location, facing west. See comments under Photo 8.



## Inspection Photos

Location Name: MONTANA STATE PC LG

#16-68HN

Location ID: 423929



**Photo 11.** Photo taken of the tank battery location, facing northeast. See comments under Photo 8.



**Photo 12.** Photo taken of the reference area to the location, west of the location, facing west. Photo illustrates perennial grass vegetation.