

# Final Reclamation Inspection

August 5, 2025

Operator: PRAIRIE OPERATING CO LLC - 10819

Location ID: 409567

Inspection Document #: 718800693

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: SHOWERS #32-11  
Location ID: 409567



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards. Bare ground and weedy annual vegetation, including kochia (*Bassia scoparia*) were observed across the location.



**Photo 2.** Photo taken of the well location, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: SHOWERS #32-11  
Location ID: 409567



**Photo 3.** Photo taken of the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: SHOWERS #32-11  
Location ID: 409567



**Photo 5.** Photo taken of ground cover at the well location. Photo illustrates kochia (*Bassia scoparia*) and evidence of drill rows from seeding.



**Photo 6.** Photo taken of the access road to the well location, facing west, towards the location. Photo illustrates that final reclamation activities have taken place, but vegetation has not yet established to Rule 1004 standards.

Inspection Photos  
Location Name: SHOWERS #32-11  
Location ID: 409567



**Photo 7.** Photo taken of the reference area to the location, north of the location, facing north. Photo illustrates perennial grass vegetation.