

Inspection Photos  
Location Name: Greenlaugh, Nauman 1-23  
Location ID: 320150



Photo 1 Tall thick vegetation through out location.

Photo 2 Wellhead sign hidden by tall, thick vegetation.

Inspection Photos  
Location Name: Greenlaugh, Nauman 1-23  
Location ID: 320150



Photo 3 Wellhead hidden by thick tall vegetation.

Photo 4 Thick & tall vegetation around the equipment.

Inspection Photos  
Location Name: Greenlaugh, Nauman 1-23  
Location ID: 320150



Photo 5 Thick & tall vegetation around the equipment.

Photo 6 Thick & tall vegetation around the equipment..

Inspection Photos  
Location Name: Greenlaugh, Nauman 1-23  
Location ID: 320150



Photo 7 Thick & tall vegetation around the equipment.

Photo 8 Thick & tall vegetation around the equipment..

Inspection Photos  
Location Name: Greenlaugh, Nauman 1-23  
Location ID: 320150



Photo 9 Thick & tall vegetation around the equipment.

Photo 10 Thick & tall vegetation around the tank battery.

Inspection Photos  
Location Name: Greenlaugh, Nauman 1-23  
Location ID: 320150



Photo 11 Thick & tall vegetation around the tank battery.

Photo 10 Thick & tall vegetation around the tank battery sign.