

Inspection Photos
Location Name: UPRR 43 Pan Am G3
Location ID: 317972



Photo 1 Vegetation through out location.

Photo 2 Wellhead sign partially covered with vegetation.

Inspection Photos
Location Name: UPRR 43 Pan Am G3
Location ID: 317972



Photo 3 Wellhead in vegetation.

Photo 4 Vegetation around the ancillary equipment.