

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 234-25 Pad

Location #: 324388



Photo # 3132 From entrance to location

Photo # 3133 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 234-25 Pad

Location #: 324388



Photo # 3134 Location



Photo # 3135 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 234-25 Pad

Location #: 324388




Photo # 3136 Location



Photo # 3137 Open ended piping on fire tube/wildlife hazard

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 234-25 Pad

Location #: 324388



Photo # 3138 Open ended piping on fire tube/wildlife hazard



Photo # 3139 Barbed wire fence needs maintenance/wildlife & personnel hazard

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 234-25 Pad

Location #: 324388



**Photo # 3140 Barbed wire fence needs maintenance/wildlife & personnel hazard**



**Photo # 3141 Barbed wire fence needs maintenance/wildlife & personnel hazard**