

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC M.B. LARSON C #1 AX PAD

Location ID: 316548

Date: 08/21/2025



Photo # 2416 Entrance to location



Photo # 2417 Location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC M.B. LARSON C #1 AX PAD

Location ID: 316548

Date: 08/21/2025



Photo # 2418 Location



Photo # 2419 Location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC M.B. LARSON C #1 AX PAD

Location ID: 316548

Date: 08/21/2025



Photo # 2428 SE corner of location



Photo # 2429 SW corner of location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC M.B. LARSON C #1 AX PAD

Location ID: 316548

Date: 08/21/2025



Photo # 2430 NW corner of location



Photo # 2431 NE corner of location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC M.B. LARSON C #1 AX PAD

Location ID: 316548

Date: 08/21/2025



Photo # 2436 Debris



Photo # 2437 Debris