

**Operator: AXIS EXPLORATION**

**Location Name: HSR-WHITEHEAD-66S62W 9SESW**

**Loc ID: 322209**

**Inspection: 713602313**



**Exhibit B**



**Exhibit B**



**Exhibit A**

**CA:** The location has not established sufficient perennial vegetation and will need to be reseeded. There are undesirable and noxious weeds that need to be controlled. The associated tank battery location was not inspected but that area will also need to be monitored and maintained. Comply with 1004 Rules.

**CA Resolution:** Operator has addressed the vegetation issue in order to comply with Rule 1004.