

**Inspection Photos**  
**Final Reclamation**  
**06/18/2025**

**Operator:** WEXPRO COMPANY- #95960

**Location ID:** 415715

**Inspection Document #:** 712300183

Moffat County, CO

Logan Maxwell  
Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: Sugarloaf Government #18 Pad

Location ID: 415715



**Photo 1.** Photo illustrates signage at the access road entrance.



**Photo 2.** Photos 2-5 show an overview of the Location, facing north, east, south, and west.

Inspection Photos  
Location Name: Sugarloaf Government #18 Pad  
Location ID: 415715



**Photo 3.** See comments under Photo 2.



**Photo 4.** See comments under Photo 2.

## Inspection Photos

Location Name: Sugarloaf Government #18 Pad

Location ID: 415715



**Photo 5.** See comments under Photo 2.



**Photo 6.** Areas remain bare with little to no vegetation growth. Straw mulch was observed, but appears to be more dense in some areas and bare in other areas. The vegetation is primarily Basin Wildrye, Halogeton, cheatgrass, and western wheatgrass.

Inspection Photos  
Location Name: Sugarloaf Government #18 Pad  
Location ID: 415715



**Photo 7.** Photos 7-8 taken of the access road. Most of the vegetation growing is Halogeton.



**Photo 8.** See comments under Photo 7.

Inspection Photos  
Location Name: Sugarloaf Government #18 Pad  
Location ID: 415715



**Photo 9.** Photos taken of the reference area vegetation, primarily sagebrush, winterfat, saltbrush, foxtail barley, and hooded phlox.



**Photo 10.** See comments under Photo 9.

