

Inspection Photos

06/27/2025

Operator: FULCRUM ENERGY OPERATING- #10805

Location ID: 437074

Inspection Document #: 712300196

Jackson County, CO

Logan Maxwell
Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Grizzly 0781 S11 Pad
Location ID: 437074



Photo 1. Photos 1-4 taken from the center of the disturbance, facing north, east, south, and west. The Location was constructed, but never drilled.



Photo 2. See comments under Photo 1.

Inspection Photos
Location Name: Grizzly 0781 S11 Pad
Location ID: 437074



Photo 3. See comments under Photo 1.



Photo 4. See comments under Photo 1.



Inspection Photos
Location Name: Grizzly 0781 S11 Pad
Location ID: 437074



Photo 5. Photo taken illustrating that gravel has not been removed, and compaction alleviation has not occurred.



Photo 6. Photo illustrates that the area appears to have been seeded, but does not meet 80% of reference area vegetation. Species include western wheatgrass and some greasewood plants.

Inspection Photos
Location Name: Grizzly 0781 S11 Pad
Location ID: 437074



Photo 7. Photo illustrates reference area vegetation, primarily rushes, greasewood, and forbs.



Photo 8. See comments under Photo 7.

