

Final Reclamation Inspection

August 5, 2025

Operator: STRACHAN EXPLORATION INC - 83130

Location ID: 331108

Inspection Document #: 718800698

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HILL #6-1
Location ID: 331108



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including kochia (*Bassia scoparia*) and cheatgrass (*Bromus tectorum*) was observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: HILL #6-1
Location ID: 331108



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: HILL #6-1
Location ID: 331108



Photo 5. Photo taken of the access road to the well location, facing west, towards the location. Photo illustrates that the access road does not meet Rule 1004 standards as bare ground, gravel, and weedy annual vegetation were observed across the road.



Photo 6. Photo taken of the access road to the well location, facing east, away from the location. See comments under Photo 5.

Inspection Photos
Location Name: HILL #6-1
Location ID: 331108



Photo 7. Photo taken of the reference area to the location, south of the location, facing southeast. Photo illustrates perennial grass and weedy annual vegetation.