

# Final Reclamation Inspection

August 5, 2025

Operator: STRACHAN EXPLORATION INC - 83130

Location ID: 330622

Inspection Document #: 718800700

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HILL #31-15-8  
Location ID: 330622



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. Bare ground and weedy annual vegetation, including kochia (*Bassia scoparia*) and cheatgrass (*Bromus tectorum*), were observed across the location.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos  
Location Name: HILL #31-15-8  
Location ID: 330622



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos  
Location Name: HILL #31-15-8  
Location ID: 330622



**Photo 5.** Photo taken of the access road to the well location, facing north, towards the location. Photo illustrates that the access road does not meet Rule 1004 standards as weedy annual vegetation were observed across the road.



**Photo 6.** Photo taken of ground cover at the location. Photo illustrates weedy annual vegetation including kochia (*Bassia scoparia*) and cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.

Inspection Photos  
Location Name: HILL #31-15-8  
Location ID: 330622



**Photo 7.** Photo taken of the tank battery location, facing west. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation, including kochia (*Bassia scoparia*) and cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, were observed across the location.



**Photo 8.** Photo taken of the tank battery location, facing southeast. See comments under Photo 7.

Inspection Photos  
Location Name: HILL #31-15-8  
Location ID: 330622



**Photo 9.** Photo taken of the tank battery location, facing east. See comments under Photo 7.



**Photo 10.** Photo taken of the tank battery location, facing north. Photo illustrates that midstream equipment remains at the location.



Inspection Photos  
Location Name: HILL #31-15-8  
Location ID: 330622



**Photo 11.** Photo taken of the reference area to the location, east of the location, facing northeast. Photo illustrates perennial grass vegetation.

