



## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 013 697 Pad

Location #: 324393



Photo # 2778 Location



Photo # 2779 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 013 697 Pad

Location #: 324393



Photo # 2780 Location




Photo # 2781 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 013 697 Pad

Location #: 324393



Photo # 2782 Location



Photo # 2783 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 013 697 Pad

Location #: 324393



Photo # 2784 Open ended piping on fire tube/wildlife hazard



Photo # 2785 Open ended piping on fire tube/wildlife hazard

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 013 697 Pad

Location #: 324393



Aug 24, 2025 at 11:30:37 AM  
+39.518492,-108.166366



Aug 24, 2025 at 11:30:43 AM  
+39.518492,-108.166366

Photo # 2786 Open ended piping on fire tube/wildlife hazard

Photo # 2787 Open ended piping on fire tube/wildlife hazard

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 013 697 Pad

Location #: 324393



Photo # 2788 Open ended piping on dehy/wildlife hazard



Photo # 2789 Open ended piping on dehy/wildlife hazard