

Final Reclamation Inspection

August 18, 2025

Operator: J W OPERATING COMPANY - 44350

Location ID: 118855

Inspection Document #: 718800746

Yuma County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: ECKLEY KITZMILLER #01-05

Location ID: 118855



Photo 1. Photo taken from the pit location, facing north. Photo illustrates that final reclamation appears to meet Rule 1004 standards.



Photo 2. Photo taken of the pit location, facing east. See comments under Photo 1.



Inspection Photos

Location Name: ECKLEY KITZMILLER #01-05

Location ID: 118855



Photo 3. Photo taken of the pit location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the pit location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: ECKLEY KITZMILLER #01-05
Location ID: 118855



Photo 5. Photo taken of the reference area to the location, south of the location, facing south. Photo illustrates perennial grass vegetation and sand sagebrush (*Artemisia filifolia*).

