

Inspection Photos
Location Name: Lyn USX MC 5-23
Location ID: 321473



Photo 1 Wellsite Location.

Photo 2 Wellhead & sign.

Inspection Photos
Location Name: Lyn USX MC 5-23
Location ID: 321473



Photo 3 Tank battery location.

Photo 4 Tank battery & sign.

Inspection Photos
Location Name: Lyn USX MC 5-23
Location ID: 321473



Photo 5 ECD Horizontal Heated Separator & Gas meter run.