


## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11B-25 Pad

Location #: 383295



Aug 24, 2025 at 2:13:36 PM  
+39.499900,-108.174838



Aug 24, 2025 at 2:18:19 PM  
+39.499982,-108.175175

Photo # 3179 From entrance to location

Photo # 3180 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11B-25 Pad

Location #: 383295



Photo # 3181 Location



Photo # 3182 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11B-25 Pad

Location #: 383295




Photo # 3183 Location



Photo # 3184 Meter calibration info not conspicuously posted

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11B-25 Pad

Location #: 383295



**Photo # 3185 Open ended piping near wellhead/wildlife hazard**



**Photo # 3186 Open ended piping near wellhead/wildlife hazard**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11B-25 Pad

Location #: 383295



**Photo # 3187 Loose barbed wire/wildlife & personnel hazard**



**Photo # 3188 Loose barbed wire/wildlife & personnel hazard**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11B-25 Pad

Location #: 383295



**Photo # 3189 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 3190 Barbed wire fence needs maintenance/wildlife hazard**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11B-25 Pad

Location #: 383295



**Photo # 3191 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 3192 Loose barbed wire/wildlife hazard**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11B-25 Pad

Location #: 383295



**Photo # 3193 Loose barbed wire/wildlife hazard**



**Photo # 3194 Loose barbed wire/wildlife hazard**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11B-25 Pad

Location #: 383295



**Photo # 3195 Loose barbed wire/wildlife hazard**