

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 236-25 Pad

Location #: 324203



Photo # 3524 From entrance to location




Photo # 3525 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 236-25 Pad

Location #: 324203



Photo # 3526 Location



Photo # 3527 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 236-25 Pad

Location #: 324203



Photo # 3528 Location

Photo # 3529 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 236-25 Pad

Location #: 324203



Photo # 3530 Open ended piping near wellhead/wildlife hazard



Photo # 3531 Open ended piping near wellhead/wildlife hazard

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 236-25 Pad

Location #: 324203



Photo # 3532 Debris



Photo # 3533 Debris

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 236-25 Pad

Location #: 324203



Photo # 3534 Methanol tank lacks required labeling



Photo # 3535 Methanol tank lacks required labeling

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 236-25 Pad

Location #: 324203



Photo # 3536 Methanol tank lacks required labeling