

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC SHARPLES MCLAUGHLIN #15 X 32 PAD

Location ID: 315626

Date: 08/26/2025



Photo # 2572 Entrance to location



Photo # 2574 Location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC SHARPLES MCLAUGHLIN #15 X 32 PAD

Location ID: 315626

Date: 08/26/2025



Photo # 2576 Emergency contact number on wellhead sign is not legible/not in compliance with CECMC rules

Photo # 2579 SW corner of location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC SHARPLES MCLAUGHLIN #15 X 32 PAD

Location ID: 315626

Date: 08/26/2025



Photo # 2580 NW corner of location



Photo # 2581 NE corner of location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC SHARPLES MCLAUGHLIN #15 X 32 PAD

Location ID: 315626

Date: 08/26/2025



Photo # 2582 SE corner of location