

Inspection Photos

08/29/2025

Operator: TEP Rocky Mountain LLC #96850

Location ID: 383144

Inspection Doc: 719200153

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 383144



Photo 1: Photos taken of the access road looking east at the location and northwest away from the location, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 383144



Photo 2: Photos taken show an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 383144



Photo 3: Photos taken show an overview of the location looking west and east, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 383144



Photo 4: Photos taken show an overview of the northern hillside, which appears to remain predominately bare except for weedy plant species such as Russian thistle.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 383144



Photo 5: Photo shows an overview of the location. Vegetation is composed of mostly fourwing saltbush and crested wheatgrass.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources