

Inspection Photos

08/29/2025

Operator: GUNNISON ENERGY LLC #10515

Location ID: 490082

Inspection Doc: 718100771

Gunnison County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 490082



Photo 1: Signage at tank/battery remains out of compliance with 605 requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 490082



Photo 2: Evidence of weed treatment observed on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 490082



Photo 3: Pipe equipment on Location has been capped, unused hose and trash/debris has been removed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources