

Audit Photos


Location Name: TEP ROCKY MOUNTAIN LLC, SAVAGE-67S94W/9SWNW

Location ID: 335043

Date: 8/28/2025



Location Overview – Photo #00511



Location – Photo #00513

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SAVAGE-67S94W/9SWNW

Location ID: 335043

Date: 8/28/2025



Location – Photo #00515



Location – Photo #00517

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SAVAGE-67S94W/9SWNW

Location ID: 335043

Date: 8/28/2025



Location – Photo #00523



Stored Equipment – Photo #00516

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SAVAGE-67S94W/9SWNW

Location ID: 335043

Date: 8/28/2025



Wildlife Entry Hazard – Photo #00518



Wildlife Entry Hazard – Photo #00519

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SAVAGE-67S94W/9SWNW

Location ID: 335043

Date: 8/28/2025



Wildlife Entry Hazard – Photo #00520



Insufficient Erosion Controls – Photo #00521