

Inspection Photos

08/22/2025

Operator: QB Energy Operating LLC #10844

Location ID: 334785

Inspection Doc: 719200164

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334785



Photo 1: Photos show the beginning and end of the disturbed area vegetation transect, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334785



Photo 2: Photos show the middle of the disturbed area transect (top left), looking northwest (bottom left) and looking southeast (top right).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334785



Photo 3: Photos show the beginning and end of the reference area vegetation transect, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334785




Photo 4: Photos show the middle of the reference area transect (top left), looking southeast (bottom left) and looking northwest (top right).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334785



Photo 5: Photos show an example of trash and debris at the location. Damaged wattles, t-posts, steel cables and barbed wire appears to be present throughout the location. Comply with Rule 606.d.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334785



Photo 6: Photos show an example of trash and debris at the location. Damaged wattles, t-posts, steel cables and barbed wire appears to be present throughout the location. Comply with Rule 606.d.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources