

# Inspection Photos

08/29/2025

Operator: TEP Rocky Mountain LLC #96850

Location ID: 323901

Inspection Doc: 719200147

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 323901



**Photo 1:** Photos show an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 323901



**Photo 2:** Photos show an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 323901



**Photo 3:** Photos show an example of undesirable plant species, cheatgrass and prickly Russian thistle, that are present on the perimeter of the working pad surface and throughout the interim areas at the location. Comply with Rule 606.c.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 323901



**Photo 4:** Photos show a sediment trap on the northern portion of the site is overtaken by undesirable plant species and requires maintenance.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 323901



**Photo 5:** Photo shows that portions of the southern interim area are progressing towards 1003 reclamation requirements. This area is dominated by green needlegrass, crested wheatgrass and Russian wildrye.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources