

# Inspection Photos

**08/20/2025**

**Operator:** BLUESTONE NATURAL RESOURCES, LLC-  
#10620

**Location ID:** 427088

**Inspection Document #:** 712300212

Routt County, CO

Logan Maxwell  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Pirtlaw Partners Ltd 24-33  
Location ID: 427088



**Photo 1.** Photos 1-4 taken from the center of the pad, facing north, east, south, and west. Vegetation observed includes Sandberg bluegrass, intermediate/western wheatgrass, Basin wildrye, and rabbitbrush.



**Photo 2.** See comments under Photo 1.

Inspection Photos  
Location Name: Pirtlaw Partners Ltd 24-33  
Location ID: 427088



**Photo 3.** See comments under Photo 1. Sign remains on the Location.



**Photo 4.** See comments under Photo 1.

Inspection Photos  
Location Name: Pirtlaw Partners Ltd 24-33  
Location ID: 427088



**Photo 5.** Photo taken from the northeastern portion of the pad, facing southwest towards the access road and remaining pad on the Location. Photo illustrates that a portion of the pad remains unreclaimed (Blue circle).



**Photo 6.** Photo taken near the entrance of the Location, facing south. Some areas remain without vegetation establishment, likely due to cattle.



Inspection Photos  
Location Name: Pirtlaw Partners Ltd 24-33  
Location ID: 427088



**Photo 7.** Photos 7-8 taken at the entrance of the access road. The cattle guard and gate remain present. Weeds, such as Bull thistle observed along the access road.



**Photo 8.** See comments under Photo 1.



Inspection Photos  
Location Name: Pirtlaw Partners Ltd 24-33  
Location ID: 427088



**Photo 9.** The access road was not apparent prior to oil and gas Operations, is approximately 1 mile in length, and will require final reclamation. (Google Earth Imagery: Top photo 8/10/2011, Bottom Photo 10/08/2024)



Inspection Photos  
Location Name: Pirtlaw Partners Ltd 24-33  
Location ID: 427088



**Photo 10.** Photo taken of the reference area vegetation north of the Location, facing northwest. Species observed include sagebrush and western wheatgrass.

