

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 24B-1 Pad

Location #: 324395



Photo # 6006 From entrance to location




Photo # 6007 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 24B-1 Pad

Location #: 324395



Photo # 6008 Location



Photo # 6009 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 24B-1 Pad

Location #: 324395



Photo # 6010 Location




Photo # 6011 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 24B-1 Pad

Location #: 324395



Photo # 6012 Open ended pipe at wellhead/wildlife hazard



Photo # 6013 Open ended pipe at wellhead/wildlife hazard

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 24B-1 Pad

Location #: 324395



Photo # 6014 Tank label has previous operators name/not in compliance with CECMC Rule 605



Photo # 6015 Tank labels have previous operators name/not in compliance with CECMC Rule 605

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 24B-1 Pad

Location #: 324395





Photo # 6016 Battery sign has previous operators name/not in compliance with CECMC Rule 605

Photo # 6017 Wellhead sign has previous operators name/not in compliance with CECMC Rule 605

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 24B-1 Pad

Location #: 324395



Photo # 6018 Sign at start of spur road to location has previous operators name