

Inspection Photos
Sam Funakoshi A2
Spill ID 486562/Remediation Project No 38349



Photo 1 – Location Photo

Photo 2 - Excavation

Inspection Photos
Sam Funakoshi A2
Spill ID 486562/Remediation Project No 38349



Photo 3 – Excavation

Photo 4 - Excavation

Inspection Photos
Sam Funakoshi A2
Spill ID 486562/Remediation Project No 38349



Photo 5 – Excavation



Photo 6 - Contaminated Soil Stockpile

Inspection Photos
Sam Funakoshi A2
Spill ID 486562/Remediation Project No 38349



Photo 7 – Contaminated Soil Stockpile

Photo 8 - Contaminated Soil Stockpile

Inspection Photos
Sam Funakoshi A2
Spill ID 486562/Remediation Project No 38349



Photo 9 – Contaminated Soil Stockpile

Photo 10 - Contaminated Soil Stockpile