

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7413 PAD

Location ID: 315328

Date: 09/2/2025



Photo # 2787 Entrance to location



Photo # 2797 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7413 PAD

Location ID: 315328

Date: 09/2/2025



Photo # 2788 Location



Photo # 2794 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7413 PAD

Location ID: 315328

Date: 09/2/2025



Photo # 2806 SW corner of location



Photo # 2807 SE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP STEELE B 7413 PAD

Location ID: 315328

Date: 09/2/2025



Photo # 2808 NE corner of location



Photo # 2809 NW corner of location