

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404323964

Receive Date:

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

Report taken by:

OPERATOR INFORMATION

Name of Operator: <u>NOBLE ENERGY INC</u>	Operator No: <u>100322</u>	Phone Numbers
Address: <u>1099 18TH STREET SUITE 1500</u>		Phone: <u>(970) 730-7281</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>		Mobile: <u>()</u>
Contact Person: <u>Dan Peterson</u>	Email: <u>danpeterson@chevron.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 33227 Initial Form 27 Document #: 403602531

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

No Multiple Facilities

Facility Type: <u>LOCATION</u>	Facility ID: <u>330713</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>HSR-KINZER-65N67W 23SENV</u>	Latitude: <u>40.387467</u>	Longitude: <u>-104.863083</u>	
	** correct Lat/Long if needed: Latitude: <u>40.385662</u>	Longitude: <u>-104.860571</u>	
QtrQtr: <u>SENV</u>	Sec: <u>23</u>	Twps: <u>5N</u>	Range: <u>67W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SM Most Sensitive Adjacent Land Use Cropland
 Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? Yes
 Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

Aquatic Native Species Conservation Waters (1202.c)
Riverine 0.06/0.24mi E
N/A
Potential PD colony within 660ft of facility

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | _____ |
| <input checked="" type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input checked="" type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | _____ |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	GROUNDWATER	NA	Lab Analysis or Field Screening, if encountered
Yes	SOILS	Refer to Tables and Figures	Lab Analysis and Field Screening

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

A site investigation was conducted during the decommissioning of HSR-Kinzer T5N-R67W-S23 L01 (aka HSR-Kinzer 4-23) Tank Battery on 3/05/2024. Laboratory soil samples were collected from the partially buried produced water vessels' (PWVs) excavations bases (FS01@4', FS02@4'). Field screening samples were collected in each cardinal direction from the sidewalls of the excavations adjacent to each vessel. The screening samples with the highest PID (SS03@3', SS05@3') were collected for laboratory analysis from the sidewalls. Laboratory samples were also collected beneath the onsite above ground storage tanks (AST01@0.5', AST02@0.5'), the flowline risers at the separator (SEP01-FL1@3', SEP01-FL2@3'), and separator dumpline (SEP01-DL@3').

Analytical results indicated that organic compound concentrations were below Table 915-1 in all confirmation soil samples collected. Groundwater was not encountered during the tank battery decommissioning.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Sampling was conducted as described in the Initial Action Summary of this Form 27. Sampling deviated from the approved sampling plan in Initial Form 27 # 403602531 because samples were collected for a second produced water vessel that was not marked on the sampling map. Sampling was in accordance with ECMC guidance. Soil samples were analyzed by a certified laboratory for the full extent of Table 915-1, including but not limited to: TPH (total volatile [C6-C10] and extractable [C10-C36] hydrocarbons) organic compounds in soil per ECMC Table 915-1, and EC, SAR, pH, boron, and Table 915-1 metals.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

If groundwater is encountered during the site investigation, a grab groundwater sample will be collected and analyzed for all organic and inorganic compounds per ECMC Table 915-1. This sample analysis includes, but is not limited to: BTEX, naphthalene, 1,2,4-trimethylbenzene (TMB), and 1,3,5-TMB by EPA Method 8260; chloride and sulfate anions by EPA Method 300.0; and total dissolved solids (TDS) by Method SM 2540C.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Visual inspection at the tank battery area occurred during decommissioning activities. Field personnel screened all disturbed areas using visual and olfactory senses to determine if laboratory confirmation sampling was required. A detailed summary of decommissioning activities, including field notes, site photos, figures, and laboratory analytical results, was attached to Form 27 # 403753673.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 9
Number of soil samples exceeding 915-1 9
Was the areal and vertical extent of soil contamination delineated? No
Approximate areal extent (square feet) 900

NA / ND

ND Highest concentration of TPH (mg/kg) _____
-- Highest concentration of SAR 0.307
BTEX > 915-1 No
Vertical Extent > 915-1 (in feet) 4

Groundwater

Number of groundwater samples collected 0
Was extent of groundwater contaminated delineated? Yes
Depth to groundwater (below ground surface, in feet) _____
Number of groundwater monitoring wells installed _____
Number of groundwater samples exceeding 915-1 _____

_____ Highest concentration of Benzene (µg/l) _____
_____ Highest concentration of Toluene (µg/l) _____
_____ Highest concentration of Ethylbenzene (µg/l) _____
_____ Highest concentration of Xylene (µg/l) _____
_____ Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected
_____ Number of surface water samples exceeding 915-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

On 03/05/24, three background soil samples were collected from one discrete location (BKG01) near the tank battery. The background data was reported in Form 27 # 403753673. After reviewing the data from the site investigation, it was determined that the samples were not collected at a sufficient distance from the impacted area and are not/will not be considered in the background analysis for this site.

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____ Volume of liquid waste (barrels) _____

Is further site investigation required?

A supplemental site investigation (SSI) will be completed to confirm the lead exceedances observed at AST01@0.5', AST02@0.5', FS01@4', FS02@4', SS03@3', and SS05@3' during decommissioning. During the SSI, soil samples will be collected and analyzed for full ECMC Table 915-1 constituents. Concurrently with the SSI, background samples (BKG02-BKG06) will be collected to determine if lead concentrations are attributed to native soil conditions at the site. Background samples will be analyzed for Table 915-1 metals, pH, EC, SAR, and boron. The proposed SSI map is attached to this Form 27. The SSI will be completed in accordance with the proposed implementation schedule, and the results of the SSI will be submitted on a subsequent Form 27.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

No impacted material caused by oil and gas operations was identified at this time.

REMEDICATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

A supplemental site investigation (SSI) will be completed to confirm the lead exceedances observed at AST01@0.5', AST02@0.5', FS01@4', FS02@4', SS03@3', and SS05@3' during decommissioning. During the SSI, soil samples will be collected and analyzed for full ECMC Table 915-1 constituents. Concurrently with the SSI, background samples (BKG02-BKG06) will be collected to determine if lead concentrations are attributed to native soil conditions at the site. Background samples will be analyzed for Table 915-1 metals, pH, EC, SAR, and boron. The proposed SSI map is attached to this Form 27. The SSI will be completed in accordance with the proposed implementation schedule, and the results of the SSI will be submitted on a subsequent Form 27.

Soil Remediation Summary

In Situ

Ex Situ

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

- _____ Excavate and offsite disposal
- _____ If Yes: Estimated Volume (Cubic Yards) _____
- _____ Name of Licensed Disposal Facility or ECMC Facility ID # _____
- _____ Excavate and onsite remediation
- _____ Land Treatment
- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Other _____

Groundwater Remediation Summary

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was not encountered during the initial decommissioning activities.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

Quarterly Semi-Annually Annually Other

Request Alternative Reporting Schedule:

Semi-Annually Annually Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report

Other Updated Site Investigation Proposal _____

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policies MWZZ316714 and MWZX316724) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.

Operator anticipates the remaining cost for this project to be: \$ 50000 _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No _____

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? _____

Does the previous reply indicate consideration of background concentrations? _____

Does Groundwater meet Table 915-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? Yes _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 03/05/2024

Proposed date of completion of Reclamation. 11/20/2026

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 10/08/2014

Actual Spill or Release date, or date of discovery. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 03/05/2024

Proposed site investigation commencement. 09/04/2025

Proposed completion of site investigation. 11/20/2025

REMEDIAL ACTION DATES

Proposed start date of Remediation. 11/20/2025

Proposed date of completion of Remediation. 05/20/2026

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

The implementation schedule has not changed from the schedule proposed in previous approved Form 27 # 404043487. The proposed supplemental site investigation (SSI) is tentatively scheduled for 11/20/2025. The ECMC will be notified of any updates to the implementation schedule in a subsequent Form 27.

OPERATOR COMMENT

This Form 27 is being submitted as an updated site investigation proposal at the HSR-Kinzer T5N-R67W-S23 L01 (aka HSR-Kinzer 4-23) Tank Battery.

The delineation borings were removed from the sampling proposed in Form 27 # 404043487. A supplemental site investigation (SSI) will be completed to confirm the lead exceedances observed during decommissioning and collect background samples. An updated proposed soil boring location map is attached to this Form 27.

The implementation schedule has not changed from the schedule submitted in Form 27 # 404043487. The proposed SSI is tentatively scheduled for 11/20/2025. The ECMC will be notified of any updates to the implementation schedule in a subsequent Form 27.

The results of the proposed SSI will be submitted on a subsequent Form 27. Per ECMC Rule 913.e., quarterly reporting will be conducted until closure criteria are achieved for the remediation project.

The request to receive notifications at Tas-Chevron-5@tasman-geo.com have been removed per denied Form 27 # 404223565.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Laura Heaton

Title: Environmental Scientist 2

Submit Date: _____

Email: Tas-chevron-5@tasman-geo.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____

Date: _____

Remediation Project Number: 33227

COA Type

Description

0 COA	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

404341943	SITE INVESTIGATION PLAN
-----------	-------------------------

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)