

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 09/2/2025



Photo # 2813 Entrance to location



Photo # 2822 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 09/2/2025



Photo # 2814 Location



Photo # 2819 Location – Tank battery has been removed

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 09/2/2025



Photo # 2839 SE corner of location



Photo # 2840 NE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 09/2/2025



Photo # 2841 NW corner of location



Photo # 2842 SW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7404 PAD

Location ID: 314978

Date: 09/2/2025



Photo # 2834 Unused flowline in meter house lacks lockout tagout (OOSLAT)



Photo # 2837 Unused flowline in meter house lacks lockout tagout (OOSLAT) Same flowline from other side