

Inspection Photos

09/4/2025

Operator: SCOUT ENERGY MANAGEMENT LLC
- 10779

Location ID: 396980

Inspection Doc: 718100781

Rio Blanco County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location ID: 396980



Photo 1: Photos taken from the south end of the Location, facing northwest and northeast. Photos examples showing areas of the Location where desirable perennial vegetation has not achieved uniform distribution or establishment. Areas remain bare or vegetated by undesirable plant species, such as halogeton.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location ID: 396980



Photo 2: Photos taken from the central areas of the Location, facing north. Photos example showing areas of the Location where desirable perennial vegetation has not achieved uniform distribution or establishment. Areas remain bare or vegetated by undesirable plant species, such as halogeton.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location ID: 396980



Photo 3: Photos taken from the the adjacent reference for comparison.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources