

Inspection Photos

09/4/2025

Operator: BAYSWATER EXPLORATION &
PRODUCTION LLC - 10261

Location ID: 315745

Inspection Doc: 718100783

Rio Blanco County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 315745



Photo 1: Photos 1-2 taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west. Photos also show areas of the Location where desirable perennial vegetation has not achieved uniform distribution or establishment. Areas remain bare or vegetated by undesirable plant species



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 315745



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 315745



Photo 3: Photos taken from the northeast end of the Location, facing southwest. Photo example showing areas of the Location where desirable perennial vegetation has not achieved uniform distribution or establishment. Areas remain bare or vegetated by undesirable plant species.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 315745



Photo 4: Photo taken from the southeast end of the Location, facing west. Photo example showing areas of the Location where desirable perennial vegetation has not achieved uniform distribution or establishment. Areas remain bare or vegetated by undesirable plant species.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 315745



Photo 5: Photo taken from the southwest end of the Location, facing east. Photo example showing areas of the Location where desirable perennial vegetation has not achieved uniform distribution or establishment. Areas remain bare or vegetated by undesirable plant species.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 315745



Photo 3: Photo taken from the west end of the Location. Photo shows cable debris remaining.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 315745



Photo 7: Photos taken from the the adjacent reference for comparison.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources